

PUBS

This is a selected list of recent pubs of interest to organizational maintenance personnel. This list was made from a computer print-out provided by the Adjutant General.

TM 3-4230-228-10 May M17 Decon
TM 5-2410-237-24 Apr D7G tractor
TM 5-3805-250-24P Mar MW24 scoop loader (w/rops)
TM 5-3820-256-10 Mar LP-12 rotary well drilling system
TM 5-4320-304-24P Nov 87 125 GPM centrifugal pump unit
TM 9-1425-601-12 Apr Touch-up painting instructions for color, camouflage pattern for marking of system support equipment (Patriot air defense guided missile system)
TM 11-5820-959-20P Jul MK-217/VRC installation kit
TM 11-5820-975-20P Dec 88 MK-2376/VRC installation kit

TM 11-5805-747-20P Apr AN/TTC-39A(V)1,2 automatic telephone central office
TM 11-6625-3151-24P Apr Test program sets for digital group multiplexers
TM 11-6625-3190-24P Apr AM-6785/U,A dual trace amplifiers
TM 55-1520-238-23P-4 AVUM and AVIM RPSTL, AH-64A
TM 55-1520-238-23P-5 AVUM and AVIM RPSTL, AH-64A
TB 9-2300-405-14 Jul Mandatory brake hose inspection and replacement-tactical vehicles
TB 55-1520-242-20-41 May SOF, emergency immediate grounding all UH-1H/V and EH-1H/X
TB 55-1520-242-20-42 May Inspection of NAS 1785-8-44 bolts, all UH-1H/V and EH-1H/X
FM 1-500 Jul Army aviation maintenance
SB 700-20 Army adopted/other items selected for authorization/list of reportable items.

AUDIO-VISUAL STUFF Available at battalion or Post Learning Center

Films, TV Tapes

TVT 9-176 M119, 105MM howitzer light towed cannon

TEC Lessons

551-101-7786-A Procedures for cancellations requests on requisitions

551-101-8090-A Process unit turn in (DS4)

551-101-8238-A Request cancellation of supplies

551-101-8239-A Maintain due-in status file for requested items

551-101-8240-A Receive supplies and equipment

551-101-8241-A Prepare and maintain hand receipt and subhand receipt files

551-101-8472-A Perform preventive maintenance on the M231 firing port weapon

580-113-6566-A Tactical communications (AN/TSC-58) power/signal cables/wires

New M3A4 Parts

The M3A4 smoke generator's fuel plug cock (shutoff valve) leaks. Replace it with plug cock, NSN 4820-01-251-8680. The old ignition cable was a bumper, too. It has been replaced by a new cable, NSN 2920-01-256-9675.

Radio Battery NSN's

If your AN/PRC-126 radio set needs a BA-5588/U lithium battery, use NSN 6135-01-088-2708. Or if you want to use a BA-1588/U mercury battery, use NSN 6135-01-094-6536. The NSN's in TM 11-5820-1025-10 are switched.

Distribution: To be distributed in accordance with DA Form 12-34-C-R, for TB-43-series.

Would You Stake Your Life *right now*
the Condition of Your Equipment?